Accused product examinations

June-August 2023

[redacted]

Serendia, LLC
Exhibit 2088
EndyMed v. Serendia
IPR2024-00842
Ex. 2088-001

Schedule

Device	Location	Proposed Inspection Date for Dr. Weide	Confirmed Inspection Date for Dr. Weide
Rohrer	The offices of Ice Miller, 1735 Market Street Suite 3900 Philadelphia, PA 1910	Tues 6/27/23	Yes (See 6/25 Email from L. Grossberg)
Ilooda/Cutera	Covington & Burling LLP law firm office, 850 10th St NW, Washington, DC 20001	Wed 6/28/23	Yes (See 6/26 Email from D. Valencia)
Jeisys/Cynosure	The offices of Leydig, 180 N Stetson Ave # 4900, Chicago, IL 60601 Contact: Leonard Z. Hua	Thurs 6/29/23	Yes (See 6/26 Email from L. Hua)
SHEnB	655 N Berry St, Suite A, Brea, CA 92821	Fri 6/30/23	Yes (see 6/27 Email from S. Corr)
Lutronic	Boston	Thurs 7/20/23	Yes (See 6/27 Email from R. Wells)
ABM	Phoenix	Thurs 8/3/23	


[redacted]


Rohrer



[redacted]

Rohrer







As shown on the following slide, the handpiece lacked an interlock, so I was able to simply probe both electrodes, one per channel. Above left is each channel and the sum waveform; above right is just the sum waveform.

[redacted]

Rohrer





[redacted]

Rohrer






Lines of pins are all wired together, then they alternate conductivity. There was no ground pad, so RF current will only flow between lines of pins.

[redacted]

Rohrer





[redacted]

EndyMed







No cart/power supply available.

[redacted]

Ilooda/Cutera









[redacted]

Ilooda/Cutera







[redacted]


Ilooda/Cutera







Ilooda/Cutera






Ilooda/Cutera









[redacted]

SERENDIA-00082895


Ex. 2088-013

CX-2939C.13

CynoSure








[redacted]

CynoSure







[redacted]