

From: Ron Cassar (JIRA) <ron.cassar@ca.flextronics.com>
Sent on: Monday, January 10, 2011 8:56:51 PM
To: Ron Cassar <Ron.Cassar@ca.flextronics.com>
Subject: [JIRA] Assigned: (SSA-1094) Touch Sluggish after rotation / a while

[<https://spe-jira.flextronics.com/browse/SSA-1094?page=com.atlassian.jira.plugin.system.issuetabpanels:all-tabpanel>]

Ron Cassar reassigned SSA-1094:

Assignee: Tong Chen (was: Ron Cassar)

> Touch Sluggish after rotation / a while

> -----
>
> Key: SSA-1094
> URL: <https://spe-jira.flextronics.com/browse/SSA-1094>
> Project: Android System Services
> Issue Type: Bug
> Environment: After merge of multi-touch patch on 12/22
> Reporter: Paul Reeves
> Assignee: Tong Chen
> Priority: Blocker
> Labels: Carrier-Demo
> Attachments: better_log.txt, sluggish_log.txt
>
>
>

> Steps to reproduce:

- > 1. Start multi-touch tester
- > 2. Touch and observe responsiveness
- > 3. Rotate phone a few times
- > 4. Touch and observe new responsiveness

> - Expected Result:

> Same as old responsiveness

>

> - Actual result:

> Sluggish touch.

> Logcat shows multiple MotionEvent log entries

>

> - Workaround (if any):

--

This message is automatically generated by JIRA.

-

For more information on JIRA, see: <http://www.atlassian.com/software/jira>

Legal Disclaimer:

The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message