



[New posts](#) [Search forums](#)

[Home](#) > [Forums](#) > **Anything saddle related** >

Mantis Bridge

Swamp · Feb 26, 2019



Swamp

Member

Joined: Jan 23, 2019

Messages: 67

Feb 26, 2019

#1

Hey guys is this a big concern on my bridge. I bought it from a member here and wanted to make sure it was not an issue.

46beee06ef287fd3e49bc40eed1cb72e.jpg

Sent from my SM-N960U using Tapatalk



bigasports

Active Member

Vendor Rep

Joined: Jan 27, 2016

Messages: 188

Location: Tennessee

Feb 26, 2019

#2

Nope your fine. Mine has a few places like that.

**JakeTrior**

New Member

Joined: Oct 29, 2014


Messages: 16

Feb 26, 2019

#3

Looks like it could be the bury protruding ? If so, you don't have to worry 'bout a thing, it's purely cosmetic

// J

**swampsnyper**

Well-Known Member

Joined: Mar 10, 2015

Messages: 4,463

Location: Warrior, AL

Feb 26, 2019

#4

Bunch it up and make sure the outer amsteel is fine. If it's just the inner bury sticking through, that's normal. If the outer amsteel is fraying, replace.

**flinginairos**

Well-Known Member

Vendor Rep

Joined: Sep 19, 2014

Messages: 3,939

Feb 26, 2019

#5

That's just the inner bury of the splice. Completely normal.

Sent from my iPhone using Tapatalk

**skyjacker**

Well-Known Member

SH Member

Joined: Nov 21, 2018

Messages: 1,466

Location: Oklahoma

Feb 26, 2019

#6

Samson recommends taping the tail on a locked brummel. On an eye splice Samson recommends taking the tape off and tapering the tail. Also on an eye splice they recommend lock stitching which keeps the tail from slipping. I'm guessing on a locked brummel the tail shifts back and forth as you tension and release causing some of the tail to pop out.

[Home](#) > [Forums](#) > **Anything saddle related** >

You must log in or register to reply here.

[Home](#)

Forums ▼

[What's new](#) ▼

[Members](#) ▼

[SH Content](#) ▼

[Log in](#)

[Register](#)

