

Prince Castle Gen. II PHU Teardown Report

Jack McCluskey

15 July 2015

Table of Contents

1. Introduction
2. Executive Summary
3. Overview
 - a. Insulation
 - b. Controls
 - c. Heater Assembly
4. Action Items


Introduction



Companies

- BKC's offices located at 5505 Blue Lagoon Drive, Miami, FL 33126
- PC's offices located at 355 Kehoe Blvd, Carol Stream, IL 60188
- PHU test restaurant ("**BK 7553**") located at 15320 N. W. 79th Court, Miami Lakes, FL 33016

Executive Summary



Overview

