

2011 Cat PM-102 Tracked Cold Planer

ITEM#

12143308

LOCATION

Boyce, Louisiana, United States, 71409



(128 - photos & videos)

Print Email Shar Shar

SOLD ON

8/22/24

WINNING BID

US \$76,000

OF BIDS

50 View Bid History

SOLD!

ITEM DETAILS	
METER READING	6,232 Hours
SERIAL #	CATPM102TZ2XXXXXX
3 ft 6 in Cutting Width, 14 in Milling Depth, 9 in Triple Grouser Track Shoes w/Rubber Pads	



IronClad Assurance



Financing

Recommendations For You Search all

					
Quantity of (2) Wirtgen WR2200 Tracked Cold Planer Kansas (1,442 mi away) US \$55,000	2012 Roadtec RX400E Tracked Cold Planer Texas (1,504 mi away) US \$75,000	2017 Bomag BM2200/75 Tracked Cold Planer Texas (1,663 mi away) US \$165,000	2010 Wirtgen W120F Tracked Cold Planer Mississippi (1,862 mi away) US \$70,000	2019 Wirtgen W220i Tracked Cold Planer Georgia (2,155 mi away) US \$200,000	2009 Cat PM201 1 Cold Planer Ontario (2,181 mi away) CAD 186,500 (U

INSPECTION REPORT

Please note that as the buyer, you are responsible for reviewing the entire inspection report when evaluating an item.

 Protected by IronClad Assurance®

GENERAL APPEARANCE

DESCRIPTION	RATING	DETAILS	
Hour Meter / Odometer		6232 hrs - No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.	
Paint			
Sheet Metal (fiberglass) Condition			
Steps/Ladders			
Hand Rails			
Exterior Lights		Operational	
 (11)			

SAFETY

DESCRIPTION	RATING	DETAILS	
Travel Alarm		Operational	
Horn		Operational	
Seat Belts		Not equipped	
Safety Lock Out/Stop		Operational	
Current Safety Manual		No	
Current Operator/Maintenance Manual		No	
 (1)			

CONTROL STATION

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

DESCRIPTION	RATING	DETAILS	
Seats/Armrests			
Mirrors			
Steering Controls			
Hydraulic Controls			
Drivetrain Controls			
Dash Console			
Engine Oil Pressure		The gauge registers in the operating range.	
Warning Lights		Operational	
Gauges		Operational	
Limited Function Check		The main components are in place and operational as noted.	
 (13)			

ENGINE

DESCRIPTION	RATING	DETAILS	
Engine		US EPA Label not legible	
Emission Label			
Blow-by (subjective visual observation)		No noticeable vapor or pressure	
Starter		Operational	
Exhaust System			
Radiator			
Oil Leaks		No dripping leaks	
Fuel Leaks		No dripping leaks	
Cooling System Leaks		No dripping leaks	
Engine - Left Side			
Limited Function Check		The engine started and ran.	
(12)			
CHASSIS			
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.			
DESCRIPTION	RATING	DETAILS	
Drive/Propel Motors		Fluid accumulation	
Final Drives			
Limited Function Check		The drivetrain was operational.	
Rotor Drive Clutch			
Rotor Drive Pulleys			
Rotor Drive Belt			
Rotor Final Drive			
Rotor Drive Brake			
Rotor Shaft Bearings			
Limited Function Check		The main chassis components functioned.	
Main Frame			
Track Frame			
Rotor Mandrel			
Holders and Cutting Bits			
Roller Frame Legs		Right front leaking	
Rotor Compartment Doors			
Conveyor Frame			
Conveyor Rollers			
Collecting Conveyor		24" Conveyor	
Discharge Conveyor			
Water Tank		Not operationally checked	
Limited Function Check		The main components functioned with minor wear throughout.	
(47)			
HYDRAULICS			

See photos for condition

DESCRIPTION	RATING	DETAILS
Pumps (Hydraulics)		
Hydraulic Motors		
Valves		
Hydraulic Tank		
Hoses		
Cylinder(s)		
Cylinder Pins and Bushings		
Limited Function Check		The hydraulic system was operational.



UNDERCARRIAGE

DESCRIPTION	RATING	DETAILS
Track Tensioners		Operational, No visible damage
Track Pads		
Grouser Height		Left Side: 28 mm, Right Side: 28 mm 
Track links		
Pins and Bushings Turned?		No 
Track Rollers		Full rock guards. Not visible. 
Idlers		
Sprockets		



Disputes:
This item is offered with **IronClad Assurance®** protection. With IronClad Assurance®, if a buyer discovers that the item is not substantially in the condition as represented in this inspection report, the buyer may submit a written dispute claim to IronPlanet. Following submission of a written dispute claim, IronPlanet will investigate the claim, re-inspecting the equipment item as necessary, and determine a fair and mutually beneficial resolution. Please note that IronPlanet inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

Rail Equipment for Sale

View Items





Get the latest auction & inventory updates delivered to your inbox!

Update email preferences
or subscribe now

IRONPLANET®

 [Need help? Contact Us](#)

 [North America](#) ▾ [English](#) ▾

Company

[About IronPlanet](#)

[About Ritchie Bros.](#)

[Careers](#)

[Blog](#)

[Terms & Conditions](#)

[Privacy](#)

[Cookie Preferences](#)

[Do Not Sell My Info](#)

[Site Map](#)

[Security Center](#)

Support

[Contact Us](#)

[How to buy](#)

[How to sell](#)

[FAQs](#)

[RitchieSpecs](#)

Our family of sites

[GovPlanet](#)

[TruckPlanet](#)

[Asset Appraisal Services](#)

[Ritchie Bros. Energy](#)

Ritchie Bros. Auctioneers

Rouse

SalvageSale

Ritchie List

Popular categories

- Truck Tractors
- Dozers
- Dump Trucks
- Equipment Trailers
- Excavators
- Agricultural Tractors
- Flatbed Trucks

Stay connected



Copyright © 1999-2025 IronPlanet, Inc. All Rights Reserved. IronPlanet®, Asset Appraisal Services™, TruckPlanet®, GovPlanet®, Ritchie Bros. Energy™, IronClad Assurance® and Auctions you can trust® are service marks of IronPlanet, Inc. All other marks and brands are the property of their respective owners.

2011 Cat PM-102 Tracked Cold Planer (Item# 12143308)



PICTURE, RIGHT FRONT CORNER

2 of 128 total photos



JUMP TO SECTIONS

General Appearance (15)
Engine (12)
Undercarriage (26)

Safety (1)
Chassis (47)

Control Station (13)
Hydraulics (14)

**Please note that as the buyer, you are*

responsible for reviewing the entire inspection report when evaluating an item.

[Return To Inspection](#)

2011 Cat PM-102 Tracked Cold Planer (Item# 12143308)



PICTURE, RIGHT REAR CORNER

3 of 128 total photos



JUMP TO SECTIONS

General Appearance (15)
Engine (12)
Undercarriage (26)

Safety (1)
Chassis (47)

Control Station (13)
Hydraulics (14)

**Please note that as the buyer, you are*

responsible for reviewing the entire inspection report when evaluating an item.

[Return To Inspection](#)

2011 Cat PM-102 Tracked Cold Planer (Item# 12143308)



GENERAL APPEARANCE - PAINT

6 of 128 total photos



JUMP TO SECTIONS

General Appearance (15)
Chassis (47)

Safety (1)
Hydraulics (14)

Control Station (13)
Undercarriage (26)

Engine (12)

inspection report when evaluating an item.

**Please note that as the buyer, you are responsible for reviewing the entire*

Return To Inspection

2011 Cat PM-102 Tracked Cold Planer (Item# 12143308)



CHASSIS - CHASSIS #9

68 of 128 total photos



JUMP TO SECTIONS

General Appearance (15)
Control Station (13)
Chassis (47)
Undercarriage (26)
evaluating an item.

Safety (1)
Engine (12)
Hydraulics (14)

**Please note that as the buyer, you are responsible for reviewing the entire inspection report when*

 Return To Inspection